

First Watch Daytime Care

The in-line store front tenant improvements required the placement of new sewer and water services. The new tenant sewer service required the placement of a 1,000-gal grease trap and the water service required an extended meter bank at the public right of way.

Topographic field investigation, Final Utility Service Improvement Plans, Plan Quantities, Estimate of Probable Cost