Harper College-Master Stormwater Report

Harper Community College Schaumburg, Illinois

The project consisted of the elimination of localized flooding on campus and adjacent private property. Hydraulic & Hydrology studies were performed to provide design standards for Stormwater management system modifications. Improvements included site re-grading and ditch conveyance channelization.

Property Condition Assessment, Conceptual Drainage Plan, Development Constraint Report, Master Drainage Studies, Constructability Reviews, Design Standards, Permit Facilitation and Compliance, Project Compliance reviews, Regulatory Compliance Review